

**Copy of the Building Safety Certificate issued by Dy. Executive Engineer, R&B Sub Division, Ankleshwar**

**BUILDING SAFETY CERTIFICATE**

No. PB-3/RSC/SRS/758/2024

Date: 04/03/2024

It is certified that the existing building **RANG INTERNATIONAL SCHOOL, ANKLESHWAR** at R.S.No.: **306, Moje – Diva, Near Skycity Bungalows, Ankleshwar** is having block/Floor as per details Below:

Details of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No. of Floor(s) in the Block	G+1	G+2	-	-	-

The building is owned/occupied by **SHREE RANG EDUCATIOAN TRUST C/O RANG INTERNATIONAL SCHOOL** have complied with the Building safety requirement in accordance with National Building code Rules, and verified by the officers concerned of **Mr A. A. Borda (Deputy Executive Engineer)** on **04/03/2024** in the presence of **Mr Pritesh Patel, Manager** and that the building/premises is fit for occupancy for running school with effect from 04/03/2024 for a period of **03 years** in accordance with rule and subject to compliance of the specific conditions as appended.

1. The certificate Issued for BAUDA - BUC permission No. BAUDA/Z-3/BUC-File No.23-22/CV/w.s./4123 to 4124 on Dated 20/12/2022.
2. Routine Maintenance will be done regularly base on Requirements.

**Issued on Dt.04/03/2024.**



**Deputy Executive Engineer  
Ankleshwar (R&B) Sub Division  
Ankleshwar**

**Principal  
Rang International School  
Ankleshwar, Bharuch.**

**Shree Rang Education Trust**  
  
**President / M. Director**